UNCLASSIFIED

AD NUMBER AD097198 NEW LIMITATION CHANGE TO Approved for public release, distribution unlimited **FROM** Distribution authorized to DoD only; Test and Evaluation; JUN 1956. Other requests shall be referred to Aeronautical Systems Center, Wright-Patterson AFB, OH 45433. Pre-dates formal DoD distribution statements. Treat as DoD only. **AUTHORITY** AFWAL ltr dtd 27 Apr 1980

AD7108 Armed Services Technical Information Agency

Reproduced by DOCUMENT SERVICE CENTER KNOTT BUILDING, DAYTON, 2, 0 HIO

This document is the property of the United States Government. It is furnished for the duration of the contract and shall be returned when no longer required, or upon recall by ASTIA to the following address: Armed Services Technical Information Agency, Document Service Center, Knott Building, Dayton 2, Ohio.

NOTICE: WHEN GOVERNMENT OR OTHER DRAWINGS, SPECIFICATIONS OR OTHER DATA ARE USED FOR ANY PURPOSE OTHER THAN IN CONNECTION WITH A DEFINITELY RELATED GOVERNMENT PROCUREMENT OPERATION, THE U.S. GOVERNMENT THEREBY INCURS NO RESPONSIBILITY, NOR ANY OBLIGATION WHATSOEVER; AND THE FACT THAT THE GOVERNMENT MAY HAVE FORMULATED, FURNISHED, OR IN ANY WAY SUPPLIED THE SAID DRAWINGS, SPECIFICATIONS, OR OTHER DATA IS NOT TO BE REGARDED BY IMPLICATION OR OTHERWISE AS IN ANY MANNER LICENSING THE HOLDER OR ANY OTHER PERSON OR CORPORATION, OR CONVEYING ANY RIGHTS OR PERMISSION TO MANUFACTURE, USE OR SELL ANY PATENTED INVENTION THAT MAY IN ANY WAY BE RELATED THERETO.

UNCLASSIFIED



WADC TECHNICAL REPORT 55-234

AD 97198



FABRICATION AND TEST OF TITANIUM JET PODS

FRED C. HOWER E. W. FEDDERSEN

CONVAIR
A DIVISION OF GENERAL DYNAMICS CORPORATION
(FORT WORTH)

JUNE 1956

WADC TECHNICAL REPORT 55-234

AD 97198

FABRICATION AND TEST OF TITANIUM JET PODS

FRED C. HOWER E. W. FEDDERSEN

CONVAIR
A DIVISION OF GENERAL DYNAMICS CORPORATION
(FORT WORTH)

JUNE 1956

AIRCRAFT LABORATORY
CHANGE ORDER 105 TO CONTRACT NO. AF33(038)-2182
PROJECT NO. 1368


WRIGHT AIR DEVELOPMENT CENTER
AIR RESEARCH AND DEVELOPMENT COMMAND
UNITED STATES AIR FORCE
WRIGHT-PATTERSON AIR FORCE BASE, OHIO

FOREWORD

This is the final report of the "Fabrication and Test of Titanium Jet Pods" program. Work was accomplished at Convair, A Division of General Dynamics Corporation, Fort Worth, Texas, in fulfillment of Change Order 105 to Contract AF33(038)2182, and at Wright Air Development Center under Project Number 1368 entitled "Construction Techniques and Applications of New Materials".

The WADC Project Engineer was Fred C. Hower. The Convair-Fort Worth Project Engineer was E. W. Feddersen. Mr. Feddersen was assisted by C. F. Crabtree of Convair Engineering and W. O. Sunafrank of Convair Tooling. This report was edited by J. R. Conder of Convair Engineering.

TITANIUM J-47 POD



ABSTRACT

Titanium alloy was substituted for stainless steel in two J47 jet pods as flight test articles. Static test articles and jigs were submitted to WADC for laboratory evaluation.

The procurement of material and the inconsistent physical properties encountered are reviewed.

Basic recommendations are given for fabrication and tooling techniques required to form, machine or assemble titanium alloy parts. Where parts and tools were extremely difficult to make a detailed description of the steps taken is given. This description includes the failures as well as successful developments.

Firm design and fabrication limitations are not given in the report due to the inconsistent material which was available. However, improvement in both surface condition and physical properties was noted in the last material received.

Titanium alloy can be fabricated into airframe parts, but high production will be difficult until a consistent material is available.

PUBLICATION REVIEW

This report has been reviewed and is approved.

FOR THE COMMANDER:

DANTEL D. MCKEE

Colonel, USAF

Chief, Aircraft Laboratory

TABLE OF CONTENTS

																							Page No
SECTI	ON I	SUM	MARY																				
	Intent Scope Result	of P	rogra	am.	•	٠	•	•	•	•	٠	•	•	•	•	•	•	•	•	•	•	•	2 3 3
SECTI	ON II	MA	TERI	AL .															٠				
	Req Pro Rec	sion cifi uire cure eivi Insp epta	cationents ment ng ar ectionce	ons. nd In on Pr	nsp	ec ed	ti ur	on es	P	ro	· ce	du:	re	• • • • • • • • • • • • • • • • • • •	•	•	•	•	•	•	•	•	9991 18995 195
SECTI	ON III	PA	RTS I	ABR	ECA	TI	ON																
	N1b Rou Saw Abr	Meta arin Reco Disc blin Reco ting. Reco Disc ch a Form	on . l Fat g mmend ussic e Cut ussic ussic nd Dr ing a king	dation dation dation dation coff on raw I	ons ons ons	on ss	o	pe	• • • • • • • • • • • • • • • • • • •	• • • • • • • • • • • • • • • • • • •	ons	• • • • • • • • • • • • • • • • • • • •	•		• • • • • • • • • • • • • • • • • • • •		•	•	•	• • • • • • • • • • • • • • • • • • • •	•	• • • • • • • • •	788 29911 222 2931 3333335 355 37
	H y d Bra Dro	ropr kefo p Ha Reco	ess F rming mmer mmend	form: Form latic	ing nin	g	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	378 389 48 48

																										Page No
	Mad	Har Jog Din hir Mil Tur Thr Dri	gl pl in Re ni ea	in in ng ng co ng di	g mme ng	end	iat	i i	ons				• • • • • • • •	•	• • • • • • • •	•	•	•	•	•	•	•	• • • • • • • • •	•	•	5556112445666666666666666666666666666666
SECTI	ON													•	٠	•	•	•	٠	•	•	•	•	•	•	30
	Rec	trod comm ced	lur	da 'e	tic Dev	ons ve]	3 。	۰	•	۰	۰	٠	•	•		۰	•	•		•	•	•	•		•	68 68 68
SECTI					GIN	-												•								
	Pro Mai Fai	commodur teri oric at I	al at	en s.	t . n.	•	•		•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	75 75 76 76 80
SECTI	ON	VI		AS	SEM	BI	Ϋ́																			
	Rec	omn	en	da	tic	ons	3 .	•	0	•	•	۰	0	•	٠	۰	•	٠	•	٠	•	•	•	•	•	8 7
SECTI	ON	VII	•	H	EAT	A. 7	NI) S	SUF	F	CI	3 :	rri	EAC	ľMI	EN?	r	PRO	CI	ESS	SES	3				
	Sur	Lim Str Ann fac Deg Cle Sur	iit es e re an	at s li T as in	ior Rel ng rea ing Fi	ns lie atm Lni	or ve en	i t	lea	ti	ing	5	01	•		·	ing	g (oqC	•	ati •	Lor •	ns •	•	•	94 95 95 95 97 97
SECTI	ON	VII	Ί	i	QUA	LI	TY	. C	ON	TF	(OI	. 1	PRO	CI	EDT	JRI	ES									
		nens ndes													•	۰	•	•	•	•	•	•	۰	•	•	100 101

																										Page	No.
	Recogn Reclai																									101	
SECTI	ON IX		STA	TI	C	TE	SI	F	RC	GF	RAN	ſ															
	Inten Scope Resul		0	۰	۰	•	0	۰	•	•	•	•	•	•	•	•	۰	•	٠	۰	•	٠	۰	•	•	105 106 11.1	
SECTI	ON X	F	LIG	HI	י י	ŒS	ST	PR	00	RA	M																
	Summa: Discus Resul	ssi	on	•	•	•	•	0	۰	۰	•	•	•	•	•	۰	•	٠	•	۰	•	•	•	٥	•	126 126 127	

LIST OF ILLUSTRATIONS

Figure No.	Caption	Page No.
1	Flight Test Pod Showing Items Fabricated from Titanium	6
2	Another View of Flight Test Fod	7
3	Typical Condition Encountered in Light Gage Sheets of RS-120 Titanium	17
4	Comparison of Typical Stress-Strain Curves for Titanium Alloy and 1/4-Hard Stainless Steel	24
5	Bend Specimens	30
6	Drawn Boxes Attempted to Obtain Comparative Deep Draw Data	3 6
7	Yoke Made by Hidraw Operation	40
Š	Another Hydropress Operation	41
9	Alloy Titanium Details and Assemblies .	42
10	Examples of Hydropress Operations	43
11	Microphoto (Magnified 10 Times) of Outer Surface of Titanium Sample	45
12	Comparative Springback Between 1/4-Hard Stainless Steel and RS-120 Titanium Alloy	47
13	Details Drop Hammer Formed From RS-120 Material	49
14	Trapping For Drop Hammer Die Forming .	50
15	Drop Hammer Operations	51

Figure No.	Caption	Page No.
. 16	Comparative Springback and Elongation Between Titanium and Stainless Steel	53
17	Results of Stretch Form Operations	55
18	Cross Section of Joggled Channel	58
19	Combination of Hydropress Operations and Steel Form Die Joggle Operations	60
20	Turning Operations on a Forged Billet	63
21	Cross Section of Cast Weld Nugget	73
22	Imperfect Forging Showing Shuts and Un-filled Areas	78
23	Forgings Produced from TI-150A Material	82
24	Two Types of Required Forgings	83
25	Forging Flash Showing Gutters and Traps	84
26	Forgings Required for Program	85
27	Parts Developing Cracks After Assembly	. 89
28	Front Spar Webs	90
29	Rear Spar Terminal Installation	91
30	Side Panels of Inter-nacelle Fairings	92
31	Examples of Drawing Operations	. 96
32	Test Jig for Front Spar Web	107
33	Rear Spar Terminal Fittings	. 108
34	Titanium Alloy Forgings with Test Jig	109
35	Static Tested Panels	110
36	Jigs Used for Titanium Alloy Bolt Tests	112
37	Test Jig for Static Testing	113

LIST OF TABLES

Table No.	Caption	Page No
I	Material Evaluation	22
II	Typical RS-120 Titanium Alloy	23
III	Static Ultimate Loads	118
IV	Fatigue Tests at Room Temperature	119
v	Static Tests	120
V(Contid)	Static Tests	121
VI	Other Fatigue Tests at Room Temperature	122
VII	Continuation of Table IV	123
VIII	Tests Run on AN Bolts	124

SECTION 1

SUMMARY

SECTION I

SUMMARY

1.1 Intent of Program

By 1950, considerable information had been gathered concerning the use of titanium alloy. However, since the material was in its infancy of development, it was natural that many contradictory statements appeared. It seemed that many of these statements were made without sufficient qualification although the basic issues were generally in agreement.

The inherent properties of titanium, particularly the high strength-weight ratio of titanium alloys, combined with its obvious design advantages, emphasized the necessity for the rapid attainment of effective manufacturing methods, processes and techniques.

With these advantages in mind, Convair proposed a program which was intended to furnish first-hand information and actual shop fabrication experience on alloyed titanium material. In addition, parts made under this program were to be incorporated into an airframe as primary structural and nonstructural members and flight tested to determine their suitability and service life.

1.2 Scope of Program

This program was established for the development of titanium alloy as a replacement material for steel in the fabrication of various structural and nonstructural parts of the J47 jet engine pod on the B-36.

The program consisted of these two phases:

- The first phase was concerned with the design and fabrication of static test articles for evaluation by the Wright Air Development Center.
- 2. The second phase consisted of the fabrication of redesigned jet pod parts and the installation of the parts in two B-36 jet engine pods. These pods were flight tested to establish data on the titanium alloy material, as compared with steel, in aircraft structures.

1.3 Results of the Program

The outcome of this program has proven that if basic techniques and procedures have been established for the material
available, titanium alloy parts can be produced under closely controlled conditions and with specialized tooling. Convair Engineering and Tooling followed this line of thinking.

Due to the great variations in the available titanium alloy, definite design and fabrication limits could not, and still cannot, be established. Only when uniform material which met established specifications was available, could production procedures and parts fabrication techniques be established.

During the course of the titanium program at Convair, considerable improvement in the quality of material received from the vendor became evident by the end of the program. Uniformity of gauge, physical properties of a higher nature, and better workability were evident. Detail parts were made with a minimum of trouble. The same parts could not be made with material received at the start of the program. The titanium producers had clearly shown that they were improving the quality of their material.

A total of 310 detail parts were fabricated from sheet material for the flight test pods and 113 sheet metal details were fabricated for the static test program.

A total of 28 titanium alloy forgings of three different types were fabricated; eight for the flight test pods and 20 for the static test program. A breakdown of the flight test pods is as follows:


Sheet metal details - 91.69 lbs/nac. Forgings 18.67 lbs/nac.


110.36 lbs/nac. or 220.72 lbs/airplane

The above 220.72 pounds of titanium alloy parts used in the two flight test pods resulted in a weight saving of 146.37 pounds in the flight test airplane.

The two flight test pods were installed on B-36 airplane No. 51 and 183 hours of flight time was accumulated during 33 flights. The jet engines were operated an average of 80 hours during this period.

Inspection of the titanium alloy parts at the completion of the tests found them to be still serviceable. (Reference Figures 1 and 2, pages 6 and ?).





7

MATERIAL

SECTION II

MATERIAL

2.1 Summary

For this program, all of the material used in the fabrication of the flight test pods and the static test articles was titanium alloy as listed below:

Sheet material - Republic Steel Corporation
RS-110 and RS-120

Forging stock - Titanium Metals Corporation - Ti-150A

Bar stock for static test bolts - Rem-Cru Titanium Inc.

Titanium Metals Corporation - RC-130B

Attempts were made to use Titanium Metals Corporation Ti-140A sheet material but the material received was not acceptable for fabrication.

Two forgings were made from Mallory-Sharon 3A1-5Cr titanium alloy forging stock but were not used although they were acceptable parts.

2.2 Discussion

2.2.1 Specifications

Since no specifications for titanium alloy material were available at the beginning of the program, a Convair procurement specification was prepared and used.

2.2.2 Requirements

The following is a list of titanium alloy material procured and used in this program:

Sheet stock

RS-120 material

- 4 sheets $.025 \times 36 \times 120$
- 1 sheet $.035 \times 36 \times 60$
- 4 sheets $.035 \times 36 \times 96$
- 1 sheet $.035 \times 36 \times 120$
- 4 sheets $.042 \times 36 \times 60$
- 3 sheets $.042 \times 36 \times 96$
- 5 sheets $.050 \times 36 \times 60$
- 1 sheet $.050 \times 36 \times 72$
- 3 sheets $.050 \times 36 \times 96$
- 1 sheet $.063 \times 36 \times 36$
- 1 sheet $.063 \times 36 \times 96$
- 2 sheets $.093 \times 36 \times 60$
- 1 sheet $.093 \times 36 \times 96$
- 1 sheet $.375 \times 36 \times 36$

RS-110 Material

- 1 sheet $.063 \times 36 \times 72$
- 1 sheet $.093 \times 24 \times 60$
- 1 sheet $.093 \times 36 \times 72$

1 sheet - $.093 \times 36 \times 84$

1 sheet - $.093 \times 36 \times 96$

Forging Billets

Ti-150A titanium alloy

14 pieces - 2 3/8 dia. x 11

12 pieces - 4 3/4 round-cornered square x 10½

5 pieces $-3\frac{1}{2}$ dia. x 9

14S aluminum

8 pieces 5 5/16 dia. x $10\frac{1}{2}$

8 pieces -23/8 dia. x 11

Titanium forging stock was specified to have the following physical properties:

Ultimate tensile strength (psi) - 150,000

Tensile yield strength (psi) - 145,000

Per Cent Elongation in 2 inches - 10

Aluminum forgings were made for the static test program so that a comparison of strengths and fatigue characteristics could be made.

2.2.3 Procurement

Following contractual approval of this program, representatives of Convair visited the facilities of Titanium

Metals Corporation, Rem-Cru Titanium Corporation, and Republic Steel Corporation to determine which of these organizations could best meet the established material specifications and delivery schedules.

As a result of this investigation, Republic Steel was chosen as the material source since their quoted delivery schedule was the only one compatible with on-time program completion. Purchase orders for titanium alloy sheets conforming to Convair's specifications were placed with Republic Steel in April 1952 for June 1952 delivery.

In accordance with Republic Steel's prior commitment, shipments were to start in the latter part of May 1952, with final shipment to be made in June 1952. A continuous follow-up was made with Republic Steel and prior to the first nation-wide steel strike in April 1952, Republic Steel advised that they would meet the June delivery. On 2 June 1952, the second steel strike was called and Republic Steel advised Convair that deliveries could not be made until after the strike. The strike ended on 26 July 1952, and Republic Steel advised Convair on 1 August 1952 that shipments would start around 15 August 1952. They further advised that complete delivery could be made in

the latter part of that month. However, only small quantities of material were received intermittently between 15 August and 1 December 1952.

In mid-December 1952, Convair was advised that some of the heavier gauges were ready for shipment and Republic Steel affirmed early delivery for the balance of the order.

On 22 December 1952, Republic Steel advised Convair that since they were experiencing further rolling difficulties they could give no definite delivery date for the balance of the material and that Convair's orders would be held on an indefinite basis.

Republic Steel airmailed to Convair a sample sheet of titanium alloy which was representative of the peculiar surface condition encountered in rolling light gauge sheets of .050 inch and under. This sample was processed to determine its suitability for use. The results of these tests indicated that the properties and surface condition of this material were unacceptable.

As a result of the material procurement problems outlined above, Convair sought to obtain the necessary material

from Rem-Cru Titanium Corporation. This alternate source was chosen because its titanium alloy is a manganese alloy similar to that produced by Republic Steel. Rem-Cru quoted a seven-month delivery schedule for the required material.

APRA was contacted by Convair and requested to aid in reducing the delivery schedule quoted by Rem-Cru. This organization was unable to effect a better delivery schedule.


A representative of Convair visited the facilities of Titanium Metals Corporation, Rem-Cru Titanium Corporation, and Republic Steel Corporation, in a further attempt to procure the required material.

It was learned that Titanium Metals Corporation could supply the necessary material from a billet on hand having physical properties which met Convair's specifications. Orders were placed for the remaining material needed and was scheduled for delivery in February 1953; however, Titanium Metals Corporation notified Convair that they were unable to roll alloy material under .047 inch thickness. It was also stated that Convair's order had been rolled four times without success and that the delivery date would be indefinite.

In early February 1953, Republic Steel solved their rolling problems and Convair received the remaining material needed except for some .063 and .093 gauge sheets. The material received possessed good physical properties except for poor surface flatness. Eleven of the seventeen sheets received were rejected because of this condition; however, as replacement material was not available and as the completion of this program was essential, the material was accepted and released for use on 26 February 1953. (Reference Figure 3 page 17)

In March 1953 Convair was advised by Titanium Metals Corporation that a portion of the material ordered would be shipped in April 1953. This material was received but from it acceptable parts could not be fabricated so the material was returned to Titanium Metals Corporation and the remaining orders were cancelled.

To complete the fabrication of all detail parts, .063 and .093 gauge material was still needed. Minimum quoted delivery for this material was 45 days and per past performance of vendors, there was no reason to believe that quoted delivery schedules would be met or that required quality would be obtained. In May 1953, Convair submitted



a request to AMC for authorization to substitute stainless steel for titanium alloy on the remaining eleven detail parts.

In October 1953, Convair was advised by AMC that Republic Steel Corporation could immediately supply the needed material. Orders were then placed for RS-110 titanium alloy to meet AMS specification No. 4908. This material was received in November 1953 and test results showed that this material was of better quality than any received during the entire program.

The remaining detail parts were successfully fabricated and the two flight test pods were completed in February 1954.

2.2.4 Receiving and Inspection Procedures

On receipt of a crated shipment of titanium alloy, each lug or crate was thoroughly checked against the shipping receipt for quantities, gauges, vendor heat identification, and sheet sizes. After the lug was opened, the packing list was compared with the shipping receipt and any variation between the shipping and packing receipts was noted.

2.2.4.1 Inspection Procedures


Inspection of titanium alloy material required the identification of each individual sheet bar, or forging, with the shipping and/or packing list. A visual inspection was made for laminations, gauge, laps, inclusions and general condition. Gauge variations between vendor markings and actual micrometer readings were recorded on a material control sheet. Each vendor's heat identification was noted and each sheet and plate was given an identifying number.

For test purposes, coupons were then removed from the new material and forwarded to Process Control for evaluation. The results of all tests were recorded on the material control sheet. This system provided a complete record of gauge variations, hardness, yield and tensile strengths, elongation at designated points, and minimum allowable bend radii by which material was designated to specific detail parts.

2.2.5 Acceptance Tests

Variances in the mechanical and physical properties of the titanium alloy received at Convair, forced the inauguration of a program of material acceptance testing prior to material release for tooling and fabrication.

All sheets of titanium received were checked to acceptance test procedures as outlined below:



The above sketch represents a typical material sheet and illustrates the type of samples and how they were taken for acceptance testing. These samples were subdivided into specimens of various sizes which were then allocated for and subjected to the following tests:

- 1. 105-degree bend at 550°F over a radius of 3 x thickness Transverse and longitudinal tests were made of all four corners of the specimen.
- 2. 105-degree bend at 550°F over a radius of 2 x thickness Transverse and longitudinal tests were made
 of all four corners of the specimen.
- 3. A chemical analysis was made of all four corners.

- 4. Tensile stress analysis (transverse) Pull coupon taken from corner No. 1.
- 5. Tensile stress analysis (longitudinal) Pull coupon taken from corner No. 2.

Several conclusions can be drawn from the results of the acceptance tests: (Reference Table II, page 23)

- 1. The spread between tensile ultimate and yield strengths is no indication of the elongation value.
- 2. The spread between tensile ultimate and yield strengths is not necessarily an index of the material's forming qualities.
- 3. Elongation is not connotative of the formability.
- 4. There was no correlation between the hardness and the strength of the specimens. (Reference Figure 4, page 24)

The following table shows typical properties of the titanium alloy material received at Convair at the start
of the program compared with the material received by
the end of the program. It can be seen that the material
received last showed properties considerably more uniform than those materials acquired at the beginning.
(Reference Table I, page 22)


TABLE I

	M	MATERIAL EVALUATION	JATION			
Date Mat'l, Received	Oct. 1952	0et, 1952	Oct. 1952	Dec. 1953	Dec. 1953 Dec. '53	Dec. 153
Mat'1. Type	RS-120	RS-120	RS-120	RS-110	. RS-110	RS-110
Sheet Gauge (In.)	.093	. 063	.093	£60°	.093	.063
Ямапдапезе	5.38	4.93	6,40	6.20	6.35	6.10
Tensile Yield Strength - psi Transverse Longitudinal	116,000	128,900 108,200	109,800	128,000 124,000	133,000 126,800	139,900
Ultimate Tensile Strength - psi Transverse Longitudinal	127,000 142,000	134,800 128,000	133,300 135,120	141,100 138,500	136,000 139,900	144,500 142,000
Elongation % in 2 Inches Transverse Longitudinal	ተ ተፒ	7 41	16 14	16 18	16 16	14 16
3T Bend Radius at 550°F Transverse Longitudinal	Fa ir Good	Good	Fa ir Poo r	Good	Good	Good

TABLE II
TYPICAL RS-120 TITANIUM ALLOY


1D F 550 F	GITUDINAL	FAIR	* POOR	FAIR	GOOD	PAIR	GOOD	G00D
2T BEND OR RADIUS AT 550 F	TRANSVERSE LONGITUDINAL	POOR	POOR	POOR	POOR	FAIR	FAIR	GOOD
3T BEND RADIUS AT 550°F	TRANSVERSE LONGITUDINAL	GOOD	POOR	GOOD	GOOD	GOOD	GOOD	GOOD
3T BE RADIUS A	TRANSVERSE	FAIR	FAIR	доов	FAIR	G00D	ФООБ	αοο υ .
ION INCHES	ONGITUDINAL	17	14	18	14	14	15	17
ELONGATION % IN 2 INCHES	TRANSVERSE LONGITUDINAL	14	16	10.5	6	7	13	15
ATE STRENGTH I	TRANSVERSE LONGITUDINAL	142,000	135,120	139,000	138,960	128,000	139,100	140,000
ULTIMATE TENSILE STRENGTH PŞI	TRANSVERSE	127,000	133,300	134,000	133,250	134,800	150,000	149,500
TENSILE YIELD STRENGTH - PSI	LONGITUDINAL	112,000	112,500	129,000	122,146	108,200	129,000	127,600
TENSILI	TRANSVERSE	116,000	109,800	130,000	128,820	128,900	127,000	144,300
CHEMICAL COMPOSITION	\$T1	94,58	33.5	-	93.58	95.03	94.394	864.46
AL COMP	£Mn	5,38	07.9	-	5.38	4.93	5.53	5.43
CHEMIĆ	æc	0,040 5,38	0.10	ı	0,040	0,040	0.076 5.53	0.072
HEAT	NO.	RIA-328	RIA-328	RIA-349	RIA-349 0.040 5.38	RIA-350 0.040 4.93	RIA-357	RIA-357 0.072 5.43
SHEET	(INCHES)	.093	.093	• 050	•050	.063	240.	2 ₀ 0°

THIS SHEET OF MATERIAL REJECTED TO VENDO



2.3 Recommendations on Material Procurement

The variances in mechanical and physical properties in titanium alloy material necessitates a program of material testing prior to acceptance and use. Each sheet should be evaluated as to forming characteristics and stocked according to an established class. Production parts should then be released against a specific class of material so that the best material will be available for severe fabrication. Such a program is deemed mandatory until the material producer is able to consistently produce material to established specifications.



PARTS FABRICATION

SECTION III

PARTS FABRICATION

3.1 <u>Introduction</u>

The use of titanium alloy for parts fabrication presented many new and complex problems. The slow rate of elongation, the resistance to bending, and compression in sheet stock, posed problems which required considerable tool development.

New tools using various means of heating were tried. Hydropress, draw press, drop hammer, and stretch forming were methods used with variable degrees of success. Due to the wide variations in material quality between each sheet and even within different areas of the same sheet, it was extremely difficult to set out specific processes and limitations. It is Convair's belief that basic procedures have been established.

Thin machining forgings and bar stock, cutter angles and cutting lubricants became very critical. Cutter life presented the primary problem due to high heat generated and the tendency of the material to cold weld to the tool.

3.2 Sheet Metal Fabrication

When a parts production order was released to the shop, all parts calling for the same gauge were reviewed. Those parts requiring severe forming were nested on the available sheet having good forming characteristics. Those parts requiring little or no forming were nested on sheets showing low formability. The forming qualities were determined from laboratory test reports.

The size blank required for each part was determined by using 1/4-hard stainless steel. By following the noted procedure and outlining each part on the suitable and available material, little waste from cutoffs was realized.

3.2.1 Shearing

Using regular production equipment, shear operations on gauges of .050 and over caused the material to separate into laminations or layers parallel to the material surface. These cracks penetrated approximately .06-inch deep and were apparent in all sheared sheet of the noted gauges.

In order to control this effect, is was necessary to band saw the blanks and parts to size. In the case of a

straight-edged part that required stretch forming, excess material was allowed on the blank and the edge was then milled to the required dimensions. While this method was acceptable on a limited program it would not be adaptable to high or full scale production. (Reference Figure 5 page 30)


3.2.1.1 Recommendations

In view of parallel cracking, it is recommended that gauges of .050 and over be sawed to the required part outline or blank size.


Blanks can be sheared provided the ruptured edge is machined after shearing to remove the laminated section. Blank and pierce operations should be limited to material of .050 thickness or under.

3.2.1.2 Discussion

Changes in shear clearance setting gave no improvement. It is hoped that research and improvement in future titanium alloy production will eliminate this tendency toward laminations. The last material received showed definite improvement and sheared satisfactorily when heated to 500°F. It is concluded that the resistance



EDGE VIEW OF BEND SPECIFIED () A STREET FAMILY SHOWING CRACKS DUE TO SHEER OPERATIONS OF COUPONS BEFORE A



SAME COUPORS AS STATES STATES AS STA

WADC TR 55-234

to shearing and the brittleness within the available material was the chief cause of the laminar separations.

3.2.2 Nibbling

Since nibbling is a form of shear operation, the same laminating tendency can be expected as in shearing. Heavy equipment is required. Nibbling offers a reasonable approach for roughing out irregular shaped blanks for forming and subsequent trim operations. In this way the laminated edge will be removed from the finished part.

3.2.2.1 Recommendations

Nibbling operations on gauges above .050 should be confined to roughing out blanks and rough-formed parts which will be sawed or milled at a later stage of fabrication to final dimensions in order to remove any laminated or separated areas.

Nibbling is a satisfactory operation on gauges under .050. Only sturdy rigid equipment should be used due to the high resistance to shearing offered by titanium alloys.

3.2.3 Routing

The high rpm of routing equipment and the high heat generated resulted in extremely short cutter life. Routing operations were not practical on titanium alloys.

3.2.4 Sawing

Both high-speed and low-speed hand sawing were investigated for sawing titanium alloy.

3.2.4.1 Recommendations

Metalloid, and cutting oil were used with the various types of saws but no improvement was noted. The table below shows the results in saw blade life using different blades, speeds, and feeds on .375-thick titanium alloy plate.

BAND SAW LIFE RELATIVE TO CUTTING AND FEEDING SPEEDS

DOALL BAND SAW Saw Type		FEED AT START In. Per Min.	SAW LIFE Per In. of Cut
1/2-inch 4 teeth per in.	85	1/2	2
1/2-inch 14 teeth per in.	100	1	3
1/2-inch 14 teeth per in.	85	1-1/4	4
1/2-inch 14 teeth per in.	60	1/2	3
1/2-inch 10 teeth per in.	60	1	11
1/2-inch 14 teeth per in.	60	1-1/4	30

In high-speed sawing, a one-inch, 14 teeth-per-inch saw was tried at 11,309 surface-feet-per-minute. This method gave unsatisfactory results; the material reached a red heat and feeding was slow. The same type saw was then tried in reverse with similarly poor results.

A one-inch, skip-tooth, 4 feet-per-inch saw, running in reverse at 11,309 surface-feet-per-minute, gave excellent results; .375 material was fed into the saw at approximately 12 inches-per-minute and produced a good smooth cut. Heat generated was low and the hardened surface produced was not over .002-inch thick. No difficulty was experienced in removing this hardened surface.

3.2.4.2 Discussion

The high-speed sawing of titanium alloy created a thin, hardened surface as noted. This surface when magnified showed fine hairline surface cracks apparently due to rapid cooling of the material. It was imperative that this surface be removed from the finished part to eliminate the possibility of further cracking under stress. This can be best accomplished by subsequent machining operations as is done on lighter gauges through filing.

Slow-speed sawing can be successfully used for heavy gauge sheet, plate stock and forgings, however, saw life is short. Feeds should be heavy to preclude the possibility of slippage and the resulting reduction of blade life.

There is a fire hazard; inflammable materials such as magnesium dust must be removed from the area before sawing titanium.

3.2.5 Abrasive Cutoff

Abrasive cutoff operations did not prove satisfactory.

Test operations on both bar stock and plate indicated that the high heat generated and the resulting hardened surface were detrimental to the cutoff operation and subsequent machine operations.

3.2.5.1 Discussion

Abrasive cutoff created a burned-hardened surface approximately .06 deep. This surface was crisscrossed with fine hairline cracks which had a tendency to spread. This surface was extremely hard and was difficult to remove. A Rockwell test for surface hardness showed an average reading of 54C. Cutoff time is slow and wear on the abrasive wheel is excessive.

3.2.6 Punch and Draw Press Operations

Normal steel form and draw dies were not satisfactory for titanium alloy material. Major problems were:


- (1) Excessive springback, even at elevated temperatures
- (2) Resistance to compression
- (3) Galling tendencies
- (4) Lubricant breakdown at elevated temperatures

3.2.6.1 Forming and Drawing

Both mechanical punch press and hydraulic draw press operations were used. Temperatures up to 1000°F were tried. It was found that titanium alloy was more difficult to draw than 1/2-hard stainless steel. Secondary sizing operations, and extensive hand work at temperatures of 500°-600°F were required.

Straight-sided parts formed on steel form and draw dies have curled side walls. Hand working at 500°-600°F is required to remove this curl to a degree to make the parts acceptable. Springback, compression bows and canned areas were problems which must be considered in parts design. (Reference Figure 6, page 36)

Consideration must be given these limitations and accept them, or provide a method of eliminating them;



THE DRAWN BOXES SHOWN ABOVE WERE ATTEMPTED USING .032 GAUGE RS-120 TITANIUM ALLOY. IN AN EFFORT TO OBTAIN COMPARATIVE DEEP DRAW DATA, THESE PARTS WERE RUN ON A HOT DIE USED FOR PRODUCTION OF MAGNESIUM PARTS. TEMPERATURES OF 550°F FOR THE UPPER PART AND 650°F FOR THE LOWER PART WERE USED WITH GRAPHITE LUBRICANT. THE FOLLOWING POINTS SHOULD BE NOTED:

- I. STRAIGHT SIDE WALL SECTIONS RETAIN THE CURL IN PASSING OVER A DRAW RADII.
- 2. THE TYPE FRACTURES INDICATED IN THE UPPER PART APPEARED THREE MINUTES AFTER COMPLETION OF DRAW. FURTHER CRACKS RADIATED FROM THE ORIGINAL FRACTURE.
 - A. DOUBLE FRACTURES FOLLOWING GRAIN DIRECTION APPEARED IN THE COMPRESSION CORNERS. NORMAL FRACTURES EXPECTED WOULD HAVE BEEN ACROSS THE CORNERS RESULTING FROM EXCESSIVE TENSION.
 - B. FRACTURES OCCURRED IN THE STRAIGHT SIDE WALL AREAS AS SHOWN IN THE END SECTION OF THE LOWER PART.

FIGURE 6

such as a bead pattern in the bottom of pans to remove the canned area and relief scallops to remove strain in compression flanges.

In a limited program such as was undertaken in the fabrication of the two jet pod assemblies at Convair, considerable hand work was utilized in straightening and completing the forming of parts. This, however, would not be acceptable on an extensive production program.

Proper lubrication, at the elevated temperatures used, was only partially solved. Molybdenum disulfide powder, both dry and mixed to a thick paste with Dow-Corning silicone grease, gave best results in reducing the galling tendencies of drawn parts.

Heated dies should be made of cast iron and the draw surfaces chrome plated.

3.2.6.2 Blanking and Piercing

As was noted in shearing operations, blanking and piercing operations also were limited to the lighter gauges of titanium alloys due to laminated material.

The use of heavy duty dies and equipment was mandatory to blank titanium alloys. While blanking and piercing

operations were very limited on the jet pod project, sufficient information was gained to establish that tool damage by these operations is considerable. Positive striping was essential. Clearances should be about the same as for mild steel. In sufficient clearances cause galling on the punch and therefore caused short life.

3.2.7 Hydropress Forming

1

Hydropress forming and Hi-Draw forming gave fairly successful results with parts normally fabricated by this procedure. It was necessary to develop springback for hydropress form blocks for each individual part as it was impossible to establish a consistent pattern of springback variations in the material. This fact contributed heavily to this problem.

In Hi-Draw forming, the tendency of the side flanges to retain the curl created when passing over a draw radii, was similar to hydraulic draw press operations.


Radii of 4T-to-6T were necessary for hydropressing and Hi-Draw operations.

Temperatures of both 900°F and 550°F were tried. The high temperature improved forming but only a slight improvement resulted from the 900°F compared to the 550°F. On the basis of these tests, all hydropress operations were run at 550°F. Heat resisting rubber pads or blankets for the high temperatures were not good. Rubber life at the elevated temperatures was short in comparison to normal cold forming rubber life. (Reference Figures 7 and 8 pages 40 and 41)

Good, clean joggles could not be formed by hydropress operation. Such joggles required development before satisfactory results could be obtained. Steel sizing die operations following hydropress forming gave best results. Scallops or reliefs were required in compression areas. These considerations should be designed into the parts. (Reference Figures 9 and 10 pages 42 and 43)

3.2.8 Brake Forming


Numerous brake bend tests, both hot and cold, were made in an attempt to establish definite bend radii. The wide variation in material quality, the low percentage of elongation, and grainy surface finish, all tended to give inconsistent results.





THE YOKE SHOWN IN THIS PHOTO REPRESENTS A HIDRAW OPERATION AT 900°F TEMPERATURE. THE MANNER IN WHICH THE BLANK SHATTERED REFLECTS THE BRITTLE NATURE OF THIS MATERIAL. THE MATERIAL USED IN THIS TEST WAS KNOWN TO POSSESS BRITTLE CHARACTERISTICS AS A RESULT OF THE MATERIAL ANALYSIS PROGRAM, AND THE RESULTS OBTAINED CLEARLY INDICATE THE FUTURE VALUE OF THIS PROGRAM. REJECTION OF MATERIAL SHOWING CHARACTERISTICS UNSUITABLE FOR SEVERE FORMING OPERATIONS WILL SUBSTANTIALLY REDUCE THE FREQUENCY OF PART FAILURES DURING PARTS FABRICATION.

FIGURE 7



ANOTHER HYDROPRESS OPERATION IS SHOWN ABOVE, THIS YOKE WAS ATTEMPTED AT 6,000 PSI, RESISTANCE TO DEFORMATION IS GREAT AND IS CLEARLY SHOWN BY COMPARISON OF THE MAGNESIUM PART "A" TO THE TITANIUM PARTS "B" AND "C". THE CRACKS IN PART "B" ARE THE RESULT OF RESIDUAL STRESS AND CONTINUED TO SPREAD THROUGH A 48 HOUR PERIOD. THESE OPERATIONS WERE PERFORMED AT TEMPERATURES OF 900° to 1000°F.





FIGURE 9

THIS SHOWS ALLOY TITANIUM DETAILS AND ASSEMBLIES REPRESENTING A GOOD CROSS SECTION OF FABRICATION TOOLING. THESE INCLUDE BRAKE FORMING, SPECIAL JOGGLE DIES, STANDARD JOGGLE SHIMS, HYDROPRESS BLOCKS, HUFFORD-TYPE STRETCH FORMING, AND STEEL FORM DIES. ALL OPERATIONS WERE PERFORMED AT 550-600°F WITH STRESS RELIEVING FOLLOWING EACH STEP OF

THE YOKE WAS ONE OF THE PRELIMINARY DETAILS CHOSEN FOR TOOL DEVELOPMENT. THE FIRST APPROACH WAS A BASIC HYDRO-Press block and then progressively through pre-form hydropress stages and hidraw tools without success. A Good part was obtained using a steel form die with a hydropress sizing operation at 6,000 psi.

THE SCALLOPS WERE REQUIRED ON THE COMPRESSION FLANGE IN ORDER TO OBTAIN A FLAT PART AND TO PRODUCE A JOGGLE WITHOUT CRACKING. THIS IS SHOWN IN THE PART ABOVE THE YOKE. THIS WAS HYDROPRESSED AT TEMPERATURES OF 550°F AND 950°F. TEMPERATURE DIFFERENTIALS HAD NO APPRECIABLE EFFECT ON FINAL RESULTS.



EXAMPLES OF HYDROPRESS OPERATIONS ARE SHOWN ABOVE. THIS PART SHOWN HAS A STRETCH FLANGE WHICH WAS SATISFACTORILY ACCOMPLISHED, BUT THE SHRINK REQUIRED AT "A" COULD NOT BE ACCOMPLISHED AT 10,000 PSI. A RELIEF WAS ACCEPTABLE IN THIS AREA AND WAS USED TO AVOID FABRICATING A STEEL DRAW DIE. FRACTURED SECTIONS AT "B" ARE THE RESULT OF ATTEMPTED HAND FORM OPERATIONS AT TEMPERATURES OF 900° TO 1000°F.

PARTS 3 AND 4 ARE EXAMPLES OF SUCCESSFUL PARTS FORMED AT TEMPERATURES OF 850° AND 600° RESPECTIVELY.

FIGURE 10


Coupons sheared for bend tests revealed the laminating or separating effect caused by shearing. It was originally believed that these cracks would deepen when bent; however, this was found not to hold true as was revealed by sectioning a number of test coupons.

The best bends were accomplished by using an electrically heated platen and heated brake dies. Temperatures in the 550°-600°F range were found to give best results. However, with material showing poor elongation it was necessary to form by staging and reheating between strikes.

Springback during brake forming was not consistent and required development for individual parts.

Heat helps reduce the springback problem and it improves the workability of titanium alloy where secondary operations are required.

The grain structure of titanium alloy became very apparent when brake formed. The bent area gave the appearance of fine cracks as an "orange peel" effect. However, a dyecheck inspection did not reveal ruptures and lab tests indicated that no adverse affects resulted. (Reference Figure 11 page 45 - this photo is to the tenth magnification.)



MICROPHOTO OF THE OUTER SURFACE OF A TITANIUM SAMPLE BENT ON ST RADIUS. THIS SAMPLE SHOWS THE CRAZED SURFACE FRE-QUENTLY EVIDENT ON COLD BEND SPECIMENS. HOT BEND SPECIMENS USUALLY SHOW A ROUGH OUTER SURFACE SIMILAR TO ORANGE PEELING, THESE CHARACTERISTICS/ARE NOT EVIDENT IN ALL MATERIAL AND DO NOT SEEM TO HAVE AN EFFECT ON MATERIAL STRENGTH SINCE THEY ARE ONLY SHALLOW SURFACE MARKS.

Stress relieving at 1000°F after braking tended to reduce the brittleness created along the bend radii and reduced the tendency of the material to creep. This is mandatory before undertaking subsequent operations such as joggling or stretch forming.

3.2.9 Drop Hammer Forming

Attempts at drop hammer forming presented many problems. Due to the resistance to bending, slow elongation and excessive springback, it was necessary to develop drop hammer dies which would allow for overforming. (Reference Figure 12 page 47

In one part, the inter-nacelle fairing, several drop hammer dies were made. The first die was with normal contour and did not give any semblance of success due to the excessive springback. As a result, a second die designed to overform the part was made. The die was heated to 400°F and the material blank to 900°F. Satisfactory results were not obtained. A die was then built with punch and die inverted from the original design. This female setup produced better results, however the parts were not acceptable. This part was then redesigned to be made in three parts using the original dies and by hand finishing to final size, acceptable parts were made.



THIS PHOTOGRAPH SHOWS THE COMPARATIVE SPRINGBACK BETWEEN 1/4-HARD STAINLESS STEEL AND RS120 TITANIUM ALLOY. THE UPPER PART IS TITANIUM. THE LOWER PART IS OF 1/4-HARD STAINLESS STEEL THE STAINLESS STEEL PART HAS THE CORRECT CONTOUR.

In order to conserve material, an angle-shaped part was formed to a closed degree on the brake. A drop hammer die having the required bend and joggle was then used to open and finish forming the part to shape. In this way, no material for trapping was required. (Reference Figures 13, 14, and 15, pages 49, 50, and 51)

3.2.9.1 Recommendations

Traps on drop hammer dies used to form titanium alloy are considerably lower than for stainless steel. The shape of these traps is more in the form of a low bead. Conventional traps are too high and cause ruptures which frequently destroy the part.


All drop hammer operations were performed by heating the material to 900°-1000°F.

Dies are run cold to eliminate mismatch.

Lead punches give satisfactory results on simple contours. Severe shapes require kirksite, or lead punches faced with mild steel.

3.2.10 Stretch Forming


Stretch forming titanium alloys can be best accomplished through the use of heated dies and form blocks. Dies for



THESE DETAILS WERE DROP HAMMER FORMED FROM RS120 MATERIAL. THE LOWER ANGLE PART IS A VARIABLE ANGLE SECTION OF SLIGHT CONTOUR AND JOGGLE IN ONE LEG. TO CONSERVE MATERIAL, THIS PART WAS BRAKE FORMED TO A CLOSED DEGREE MERLE, THEN SIZED ON A DROP HAMMER DIE, RESULTING IN SAVING IN TRAPPING MATERIAL NORMALLY REQUIRED IN DROP HAM. FIGURE 13

WADC TR 55-234

49



WADC TR 55-234

50




FIGURE 15

DROP HAMMER OPERATIONS ARE SHCWN ABOVE. THESE OPERATIONS WERE PERFORMED USING 900°F TEMPERATURE FOR THE TITANIUM MATERIAL WITH THE KIRKSITE DIE HEATED TO 400°F. HAMMER TECHNIQUE IS OF PRIME IMPORTANCE IN THESE OPERATIONS.

PART "A" SHOWS TH CONFIGURATION OF MATERIAL AND THE TRAPPING USED TO PRODUCE THIS PART.

PART "A" ALSO SHOWS CRACKS IN NON-STRESSED AREAS OF THE MATERIAL. THIS IS FURTHER INDICATION OF THE

PECULIARITY OF THE TITANIUM ALLOY.

formed sections must be built from material which can be heated to 600°F. Skin stretching can be accomplished at 450°F; skin stretch form blocks can be cast from kirksite. However, steel or aluminum should be used in the construction of section forming tools. The form blocks must be developed for springback. (Reference Figure 16 page 53)

The rate of elongation in stretching, even under elevated temperatures, is very low as the material must have time to move.

Strain hardening and material creep after forming also presented a fabrication problem. Material that had been formed to contours, when permitted to lay at room temperature 24 to 48 hours, showed a decided change in contour. Parts frequently developed cracks after 24 to 48 hours following stretch forming operations. Immediately after forming stress relieving at 1000°F for 30 minutes gave partial relief. All formed parts were given this stress relieving operation. The above conditions were worse when parts were stretch formed cold.

All stretch forming operations of preformed section parts were carried out by heating the form block to 600°F.




FIGURE 16

COMPARATIVE SPRINGBACK AND ELONGATION BETWEEN RSI20 TITANIUM ALLOY AND ONE-FOURTH HARD STAINLESS STEEL SHOWN ON THESE STRETCH-FORMED PARTS. THE CENTER PART IS RSI20 TITANIUM ALLOY AND THE UPPER IS STAINLESS STEEL STAINLESS STEEL PART IS OF THE CORRECT CONTOUR. ELEVATED TEMPERATURES DID NOT CORRECT THIS PROBLEM. PARTS "A" AND "B" ARE TITANIUM ALLOY; BOTH WERE BRAKE-FORMED AT 550°F AND COLD STRETCH FORMED.

WADC TR 55-234


This was accomplished by use of a suitable gas burner under the block. The part was very slowly wrapped permitting it to absorb the heat on contact with the form block. A dwell time of one-to-one and one-half minutes after wrapping to permit full heat absorption was found beneficial. The contour was then set by stretching approximately two per cent. By holding the part under full pressure against the stretcher form, creep was reduced.

Hot brake forming of preformed sections improved the stretch form operation.

Localized necking or reduction in flange width was also encountered while no loss in gauge was experienced; loss in flange height in localized areas was noted. This was especially noticeable in sharp bend areas. In order to overcome this problem, excess material was added to the flange width. This excess was removed after forming. (Reference Figure 17, page 55)

3.2.11 Hand Forming

While no titanium alloy parts were fabricated by hand forming alone, considerable hand work was required for finishing various parts to required dimensions.



55

Due to the inconsistent results obtainable from the available material, hand finishing formed an important link in completing this project. The varied amount of springback, the curled flanges on draw formed parts, and the creep tendency of titanium alloys all combined to make hand finishing a necessity.

Hand work is a slow, difficult process. While hand work is acceptable on a limited project, such as replacing the stainless steel in the two J47 jet pod assemblies, it would not be acceptable on an extended production program.

All hand work was carried out by localized heating to 500° - 600° F. By using suitable mandrels and heavy lead-faced hammers, it was possible to displace the material to the extent required for acceptance on assembly.

The use of hand and hydraulically actuated arbor presses was necessary on the heavier gauge materials. Using temporary type blocks and localized heating, pressure was exerted in the distorted areas until the required correction was obtained.

In order to reduce creep and strain hardening effects, stress relieving at 1000°F shortly after forming operations were completed, was utilized.

3.2.12 Joggling


Considerable difficulty was encountered in attempting joggle operations. Only steel joggle dies gave any semblance of success. Heating both the dies and material to 600°F and then over-forming resulted in an acceptable offset.

However, it was found necessary to extend the length of joggle travel to five and six times the depth to prevent cracking. In some parts this was not acceptable and a relief cutout, when acceptable, was incorporated to permit the necessary deflection.

The entire section must be joggled for good results.

The side wall offers too much resistance to compression when only the top flange is joggled. (Reference Figure 18 page 58)

Some joggling was attempted on parts formed on the drop hammer. Here, too, it was found necessary to over-form to allow for springback. It also was necessary to increase



WADC TR 55-234

the length of joggle travel and to utilize heating to 600° F. The strains set up during joggle operations frequently will lead to cracks and distortion of the flat plane of the part. Where acceptable, this can be reduced by incorporating a relief cutout or joggling both planes of the part.


In order to reduce brittleness and ruptures following joggling, it was found beneficial to stress relieve at 1000°F shortly after completing operations. (Reference Figure 19, page 60)

3.2.13 Dimpling

Titanium alloy dimples fairly well considering the difficulties encountered in other fabricating phases of the project. The chief requirement is adequate heat, and sufficient power for forming the dimple.

Equipment used in dimpling magnesium is suitable for dimpling titanium alloy. All burrs and sharp edges around holes to be dimpled must be removed in order to eliminate every possibility of cracking the material.

In dimpling operations a temperature of 600°F was used. Permitting a short dwell time before actual dimpling



WADC TR 55-234

to permit heat absorption, coupled with a slow ram descent, gave good results. Cracking usually could be traced to incomplete deburring, insufficient heat or too quick a ram thrust. Only very slight hole enlargement was noted; this compared favorably to stainless steel.

3.3 Machining

Machine operations required the development of cutters, machining techniques, and coolant applications.

Ridigity of machine and set-up are important factors of machinability. These factors should be continually stressed.

Cutting lubricants became critical as did cutting feeds and speeds. Highly chlorinated cutting oils have benefited cutter life and surface finish. Operations were not extensive enough in scope to be conclusive but indicated that highly chlorinated oils increase cutter life up to 300 per cent. (Reference Figure 20, page 63)

3.3.1 Milling

Face mill and slab mill operations produced good surface finishes. With the Ti-150 and Mallory-Sharon 3AL-5CR alloy forgings, cutter life with high speed steel or

carbide compares with that when cutting aircraft steel SAE4340 heat treated from RC42 to RC44.


Cutting oils are more critical for titanium than for steel, which makes the selection of a proper cutting oil so important.

Cutters with positive rake angles produced both better cutter life and better finish. Cutter speeds of 35 to 40 surface-feet-per-minute for high speed steel, and 80 to 100 surface-feet-per-minute for carbide, gave the best cutter life.

Rigidity of machine and machine set-up is just as important for mill operations as for any other machine operations.

3.3.1.1 Recommendations

Positive rake angle tools similar to those used for aluminum should be used. Carbide should be used for cutting tools whenever possible, and all milling operations should be run with a proper cutting oil. Rigid machines and machine set-ups should be used at all times.



THIS PHOTOGRAPH SHOWS TURNING OPERATIONS ON A FORGED BILLET. THE HEAVY FEEDS SPECIFIED IN MOST REPORTS WERE NOT SUCCESSFUL BUT FEEDS OF .008 TO .010 WERE SATISFACTORY. THE GROOVE IN THE LARGE END OF THE BILLET INDICATES AN UNSUCCESSFUL ATTEMPT TO CUT THE BILLET USING AN ABRASIVE CUT-OFF WHEEL. THE CUTS ON THE UPPER SURFACE OF THE BILLET WERE ACCOMPLISHED USING A FACE MILL.

FIGURE 20

3.3.2 Turning

Surface scale approximately .040-inch was encountered on round bar stock. A 100 surface-feet-per-minute at a feed of .005 PR produced the best results. Standard grade carbide tools gave little success as the tool had to be ground after each cut. Best results were obtained with a K3H Carboloy cutting tool ground with a positive rake and clearance angle.

After the hard scale was removed, machining was comparable to 18-8 stainless steel. On the basis of this test, all turning operations were accomplished on the production parts.

3.3.3 Threading

Twenty-four holes were tapped with a standard 3/8 x 16 tap ground for cutting steel. Speed was 20 rpm, approximately two surface-feet-per-minute. Cimcool was used in its concentrated form as a lubricant for tapping. At this speed tapping was accomplished with comparative ease. A faster speed of 31 rpm was then tried with little success. The tap would squeak and bind and eventually break at this speed. At the slower speed, the 24 holes were finished with no apparent wear on the tap.

Based on this experience, it is estimated that the tap should have a life of 200 to 300 tapped holes.

3.3.4 Drilling

High-speed drills stand up well at speeds of 20 to 25 surface feet-per-minute with feeds of .002 to .003 inches per revolution using sulphur-base cutting oil as the coolant. Increase in speeds or in feed rate reduces drill life.

The speeds and feeds as used for carbon steel tools on cast steel material serve as a fair guide for titanium drill operations.

In drilling sheet titanium, such as detail parts for assembly operations, it is imperative that pressure be maintained in order to assure constant cutting action. Otherwise, heating and work-hardening will become a problem.

Air-pressure operated hand drills are preferred to electrically powered drills because of their lower speeds and the constant control of their speeds in drilling.

3.3.5 Profiling

Profiling operations on .375 plate were accomplished on a Cincinnati Hydrotel at 356 rpm using a high-speed steel end mill. Cimcool was used on all cutting operations as a coolant.

The roughing cut was made at seven inches per minute. The finish cut was made at four inches-per-minute feet with the removal of approximately 1/32 inch material. The finish produced by this profiling operation was very good.

RESISTANCE WELDING

SECTION IV

RESISTANCE WELDING

4.1 <u>Introduction</u>

In view of the lack of information on spot welding titanium alloy, it was decided to investigate its welding potential on both ac and dc type spot welding machines.

In the past Convair had used a minimum tensile over-shear ratio of 0.25 as a control factor. It was decided that this T/S ratio would be the target for this work. All work was accomplished using RS-120 titanium alloy.

4.2 Recommendations

Until such a time as material properties such as hardness, surface finish, chemical analysis, tensile strength, etc. becomes uniform, spot welding of RS-120 does not appear feasible.

4.3 Procedure Development

Using stainless steel settings as a starting point, a parameter of 27 spot welds was run on both the Acme ac and the Taylor-Winfield dc machines. These welds were macrosectioned and examined for nugget size, penetration, and soundness.

On the basis of the macroexamination of the above welds.

several machine settings were chosen for both ac and dctype spot welders. Tensile and shear coupons were made at these settings and tested.

The nuggets of all of the welds produced were surrounded by a heat affected zone in which certain metallurgical changes had taken place that were not fully understood.

It was considered possible that absorption of oxygen, carbon or nitrogen might be a cause for the embrittlement of the welds. To explore this possibility, welds were made on both types of machines using argon gas to envelope the faying and electrode surfaces. The results did not show any appreciable change.

T/S ratios in the order of 0.19 were obtained. All spot welds having a shear load of greater than 1200 pounds showed expulsion of the hot metal at the interface of the weld. It is possible that this expulsion was correlated to the low tensile values of these high shear welds.

A third type machine (three-pase dc) was tried. This machine is capable of welding a wider range of materials because of the added controls and closer control over existing variables.

The results obtained from this machine proved very encouraging. The shear strengths were better than that required for one-half hard stainless steel and the tension strengths were considerably better than those obtained previously.

The welds were still somewhat brittle, but they lost the extreme brittleness which characterized the previous welds. As stated before, early welds had a concoidal fracture and broke through and around the welds indiscriminately. The welds made with the three-phase machine had ductile type fractures and the entire nugget was pulled from both coupons. The nuggets greatly resembled those found in the stainless steel.

All of the above tests on the three-phase machine were accomplished using material from one sheet: When the parameters for the best settings were investigated, to improve the weld quality and to determine the critical limits, the original results could not be duplicated with material from a different sheet of material. In fact, it was found that welds could not be consistently reproduced in different areas of the same sheet.

The following is a summary list of the difficulties involved in the spotwelding of RS-120 titanium alloy.

- 1. The spotwelding characteristics of RS-120 sheet material varies from sheet to sheet. It was not possible to reproduce results from one sheet to another. Machine settings which gave good results on one sheet, had to be varied more than the 10 per cent allowed on other sheets. Each sheet was a separate problem, involving the determination of a new set of machine settings. This procedure is not too involved but could require a certification for each sheet to be spotwelded.
- 2. The problem of varying sheet thickness involved the further consideration of certifying for various thickness in the same sheet.
- 3. The problems involved in spot welding RS-120 titanium alloy were undoubtedly a function of the variations found in the sheets such as:
 - A. Variation in surface finish
 - B. Variation in hardness (24 to 36 Rockwell "C")
 - C. Variation in chemical composition Manganese varied from 4.93 to 8.01 per cent, carbon varied from 0.04 to 0.10 per cent

- D. The tensile strength varied from a low of 127,000 psi to a high of 158,300 psi.
- 4. The machine settings must be held very close and were difficult to establish. The only way to determine the settings is to use an oscillographic record to determine the relationship between current and forging time.

 This was found to vary from sheet to sheet.
- 5. The RS-120 titanium alloy appeared to have a shunting effect which was much more predominate then the same effect in stainless steel. When multiple spot welds are made, the settings obtained for one spot weld would have to be varied considerably to produce satisfactory welds.
- 6. When multiple sheets are to be spot welded, the machine settings will have to be adjusted to facilitate welding the sheet in the combination with the poorest spot welding characteristics. (Reference Figure 21, page 73)

THE CROSS-SECTION OF THE CAST WELD NUGGET ABOVE SHOWS THE COLUMNAR STRUCTURE OF THIS TYPE WELD. BRITTLENESS IS INDICATED BY THE FRACTURE OCCURRING IN THE HEAT AFFECTED ZONES AND BY THE LACK OF ELONGATION IN THE WELD AREA. ALL STRESS TESTS ON VARIOUS MATERIAL SHEETS SHOWED THIS TYPE WELD.

SECTION 5

FORGING

SECTION V

- 1

FORGING

5.1 Recommendations

Apparently, the forging of titanium is no more difficult than the forging of 75S aluminum; however, more preliminary stages are needed in the dies than are normally used in forging steel. The dies for all of the titanium forging operations were heated to between 240° - 300°F. This temperature was maintained throughout the forging operations.

It is recommended that billets be ground before forging to remove surface imperfections. While such imperfections apparently are not severe enough to cause defects in the forged part, a better finished part is obtained from the ground billet.

5.2 Procurement

In the future when it becomes necessary for Convair to specify the size of billet which will be used for titanium forging, such sizes should be from three-to-five per cent less in cross-sectional area than that used when making the same forging from steel. This is necessary because

normally three-to-five per cent is lost in scale on steel parts which is not the case with titanium.

5.3 <u>Materials</u>

Forging billets were furnished by Titanium Metals Corporation and Mallory-Sharon Titanium Corporation. Those billets furnished by Titanium Metals Corporation carried their specification of Tl-150, while those furnished by Mallory-Sharon Titanium Corporation carried their specification 3AL-5CR alloy. The surface conditions of the billets appeared very rough. Convair suggested that these billets be ground, however Titanium Metals Corporation stated that this would be unnecessary.

5.4 Fabrication

The forging of titanium was accomplished in two forging hammers. The edging and blocking was accomplished in a 8,000-pound steam hammer and the finishing was accomplished in a 5,000-pound steam hammer. It was felt that the breaking down of the billet would require more power than the finishing because of the inherent tendency of titanium to resist compressions. It was also felt that less flow-through would be encountered in the finishing die if it were accomplished on a smaller, or 5,000-pound hammer.


The following is a detailed procedure of the forging of each individual titanium part. (Convair part #36P10354)

Part No. 1 was heated at 1640°F and carried at this temperature all the way through the forging operation. The part did not fill and there were shuts on the rib sections. (Reference Figure 22, page 78)

Part No. 2 was heated at 1640°F, fullered, rolled, reheated to 1600°F, blocked, and finished, reheated to 1700°F, restruck in the final stage and trimmed. Considerable difficulty was encountered in trying to fill all parts of this forging.

Part No. 3 was heated to 1640°F, fullered, rolled, and reheated to 1700°F, reblocked and finished, reheated to 1700°F and restruck in the finish die. There was very little reduction of cross-sectional area in restriking in the finish die.

Part No. 4 was heated to 1850°F and carried all the way through the forging operation; however, the part cooled before it could be trimmed, therefore it was reheated to 1200°F and trimmed.



Part No. 5 - Same as part No. 4 except it did not require reheating for trimming.

Part No. 6 - Same as part No. 4.

Part No. 7 - Same as part No. 4 except a longer tong hold was drawn on the billet. This was to reduce the volume of material. The billet was flattened on two sides reducing it to approximately 4 3/8 inch. The part did not require reheating for trimming.

Parts Nos. 8, 9, 10, 11, and 12 - Same as Part No. 4 except no reheating for trimming was required.

Convair Part No. 36F10353 - All 15 of the titanium parts were handled in the same manner. They were heated to 1670-1700°F, carried all the way through the forging operations, trimmed, and restruck in the finish die. There was one shut apparent in all these forgings but this was unimportant to the finished part.

Parts Nos. 16 and 17 of the same Convair number were forged from stock which was furnished Convair by Mallory-Sharon Titanium Corporation as a sample. These billets were heated to 1850°F and handled in the same manner as the preceeding 15 parts.

Convair Part No. 36P10356 - All five of these titanium parts were heated to 1070°F and carried at that temperature all the way through the forging operations. These apparently were the most successful forgings made.

5.5 Heat Treatment and Processing


The temperature in the furnace for the titanium forgings was controlled by a portable potentiometer and an optical pyrometer.

The dies for all the forging operations were heated to between 240-300°F. This temperature was maintained throughout the forging operations.


Heating of the billets was based on the recommendations of a metallurgist for Titanium Metals Corporation. It was originally intended not to heat the billets above 1670°F and that all forging operations were to be accomplished before the temperature dropped below 1350°F. However, seeing the amount of reduction accomplished in these forging operations it was felt that the higher heating was acceptable for the initial heat, and reheat as many times as necessary to make the part so long as there would be at least 15 per cent reduction in cross-sectional area between each heat. It was stated that this would insure the physical properties.

Billets were placed in an electric heat-treat furnace and brought up to 1400°F before placing in the forging furnace.

It was recommended that the forgings be stress relieved at 1200°F for a period of 48 hours and then air cooled. This operation was satisfactorily accomplished at Convair. (Referce Figures 23, 24, 25, and 26, pages 82, 33, 84, and 85)



WADC TR 55-234




WADC TR 55-234

FORGING FLASH SHOWING GUTTERS AND TRAPS USED TO RESIST LATERAL FLOW.

FIGURE 25

84

FIGURE 26



WADC TR 55-234

SECTION 6

ASSEMBLY

SECTION VI

ASSEMBLY

6.1 Recommendations

The assembly of titanium alloy details presented problems not normally encountered in assembly operations.

It is important that detail parts be formed to the exact required diminsions. Assembly of parts under strain, created stresses within the assemblies which frequently developed into cracks. The cracking of parts after assembly usually occurred in those details which were formed from material having low elongation, and high ultimate tensile strength. Stress relieving all parts to reduce brittleness and forming strains became mandatory. (Reference Figure 27, page 89)

Torque created in bolting sheet metal parts created strain which resulted in cracking. It is important that holes drilled through such assemblies, both for bolts and rivets, be at 90 degrees. When holes are drilled off-angle to the surface plane, and bolts and rivets drawn up tight, uneven strains are created which leads to material cracking after assembly. The experience gained in the assembly of the two J47 jet pods, pointed out the necessity of properly formed parts, stress relieve, and for the attention to details in

assembly operations. All are important points in making acceptable assemblies from titanium alloy materials. (Reference Figures 28, 29, and 30, pages 90, 91, and 92)





FIGURE 27

ABOVE ARE THREE PARTS WHICH DEVELOPED CRACKS SEVERAL DAYS AFTER ASSEMBLY. PRECAUTIONARY STRESS RELIEF OPERATIONS HAD BEEN PERFORMED. LATER THESE PARTS WERE MADE WITH NO SUBSEQUENT DIFFICULTIES RESULTING.




WADC TR 55-234



THE REAR SPAR TERMINAL INSTALLATION PICTURED HERE IS ONE OF THE TWO SUPPORT POINTS FOR THE ENTIRE JET POP NACELLE ASSEMBLY. THE FOUR HEAVY PLATES (.375 INCH THICKNESS) AND THE CENTER FORGING ARE TITANIUM ALLOY.

ÜĴ





HEAT AND SURFACE TREATMENT PROCESS

SECTION VII

HEAT AND SURFACE TREATMENT PROCESSES

7.1 <u>Heat Treatment</u>

The heat treatment of titanium alloy, except as noted for forgings, as commonly interpreted, was not used. However, the application and use of heat throughout the fabrication processes was used where it proved beneficial. The application of heat in sheet metal fabrication definitely demonstrated that ductility could be improved.

7.1.1 Limitations on Heating for Forming Operations

In the application of heat for forming of titanium alloy, a maximum of 1000°F was established. Temperatures above 1000°F created a scale which was difficult to remove completely. It is felt that temperatures above 1000°F should be avoided.

Throughout the fabrication procedures definite temperatures were noted for forming operations. Such temperatures were established as the most suitable and gave the most consistent results for a given operation. However, due to the wide variation in ductility of titanium alloy, it was frequently necessary to deviate from established temperatures.

7.1.2 Stress Relieve

Stress relieve of titanium alloy was accomplished in a salt bath, as was used for the heat treatment of aluminum alloys, at 900-925°F. The parts were immersed for a period of 30 minutes maximum and then slowly cooled at room temperatures. An alternate method of heating in an electrically controlled hot circulated air oven at 1000°F for a maximum of 30 minutes, and then cooling at room temperatures was used. (Reference Figure 31, page 96)


7.1.3 Annealing

Due to the lack of facilities necessary to anneal parts in an inert atmosphere, it was impossible to anneal titanium at the required temperature. As a result, only a partial anneal was accomplished at the temperature and techniques given for stress relieving.

7.2 Surface Treatment

7.2.1 Degreasing

The removal of lubricants, dirt, oil, grease, etc. was accomplished by vapor degreasing and followed by an alkaline electro-cleaning operation. This is an anodic cleaning process using an alkaline-water solution at a temperature



GOOD AT THE TIME OF THE DRAWING, THE CRACKS IN "B" AND "C" APPEARED APPROXIMATELY 12 HOUR'S LATER AND CON-TINUED TO GROW THROUGH A 4 DAY PERIOD INDICATING INTERNAL STRESS. PART "D" WAS STRESS RELIEVED AT 750°F AT THE TIME MATELY 39%. PART "A" FRACTURED DURING THE DRAWING OPERATION. THIS PART WAS FROM A DIFFERENT SHEET OF MATERIAL THAN PARTS "B", "C", AND "D", WHICH INDICATED THE INCONSISTENCY ENCOLUNTERED OF THAN PARTS "B", "C", AND "D", WHICH INDICATED THE INCONSISTENCY ENCOLUNTERED. IN THIS THAN INTO ALLOW. EXAMPLES OF DRAWING OPERATIONS ARE SHOWN ABOVE.

of 180-200°F for 1-to-3 minutes followed by a clear water rinse and air drying.

7.2.2 Cleaning

The lead pick-up from drop hammer operations was removed from the titanium alloy parts by immersion in a concentrated nitric acid or a 50 per cent (by weight) nitric acid solution in water for a period of time not exceeding 15 minutes. The titanium alloy was attacked a negligible amount by the acid solution when immersed for 15 minutes.

The removal of scale or discoloration formed at temperatures up to 1000°F were readily removed by immersion, at room temperature, in a solution of 8 per cent by weight nitric acid, 2 per cent by weight hydrofluoric acid and the balance water. The immersion time was held as short as possible, due to the rapid material loss and never exceeded a maximum of two minutes.

7.2.3 Surface Finishes

Surface finishes were treated, in general, the same as for stainless steel. The following is an excerpt from the finish specification for the titanium alloy pod project.

"Parts made from titanium alloy shall be insulated from magnesium and aluminum alloys. An acceptable insulation is two coats of zinc chromate primer, MIL-P-6889A,

Type I, applied to the faying surface of titanium alloy in conjunction with the normally required paint coatings on the aluminum and magnesium. The primer coatings on the titanium shall extend at least one-half inch outside the faying edge on interior surfaces and up to the faying edge on exterior surfaces."



QUALITY CONTROL PROCEDURES

SECTION VIII

QUALITY CONTROL PROCEDURES

8.1 <u>Dimensional Control</u>

When an order for the production of parts was ready for release to the shop area, the material having the acceptable characteristics for the operations to be performed was removed from stock. The pertinent information, such as actual gauge, vendor heat number, and sheet number was entered upon the production order. The material sheet was then forwarded for reduction to the required blank sizes.

Each forming operation which could result in a gauge loss, required an additional inspection operation. Parts showing a loss in excess of 10 per cent of the required gauge were rejected for material review board disposition.

After completing the final fabrication operations and inspections, acceptable parts were forwarded for cleaning operations. There, the parts were vapor degreased and then cleaned by lightly etching in acid bath cleaning solution for lead pickup and heat scale removal. Due to the etching action of the acid bath, considerable gauge loss was experienced during the cleaning operations. As a result the

parts were again inspected for gauge loss and parts 10 percent under the required gauge were rejected.

8.2 Nondestructive Testing

Following the cleaning and the subsequent inspection operation the parts were forwarded for a penetrant inspection. The parts were immersed in a fluorescent solution for 30 minutes, then removed and wiped dry. The parts were then exposed in a darkened room to a fluorescent light beam. Any crack, flaws or other minor ruptures were revealed. Such defects generally were not visible to normal visual inspection. Parts which showed such defects were rejected for material review board action.

8.3 Recognition of Material Defects

Titanium alloys, as were available for this project, had various defects which usually are not present in other aircraft materials.

One of the most serious defects was brittleness and poor elongation. Such defects were the prime causes for material loss during forming of sheet metal parts due to cracking and severe stress hardening. Poor elongation and brittleness could be determined by laboratory tests. This type of defect was usually confined to an individual sheet and when

such was determined the sheet was segregated and released for production of parts requiring little or no forming. If this condition was too severe, the material was rejected and not used on the project.

Laps, laminations, and flaws were present in the available titanium alloy materials. Such conditions were not always visible until after forming or machining operations were begun. In sheet metal, such defects usually caused ruptures and a substantial loss of material.

Over-gauge material caused considerable trouble during forming operations, particularly on steel form dies. Due to the close draw clearance required in constructing good form dies, this over-gauge material caused binding and increased the galling tendency.

Much of the sheet stock received showed a poor surface finish. While no material structural quality was discernable because of this condition, it did increase friction and galling during forming.

8.4 Reclamation of Rejects

Because of the extreme shortage and high cost of titanium alloys, no material was rejected that could be utilized.

Every effort was made by collaboration between inspection, engineering, tooling and shop personnel to use the available material.

Material which developed a defect after forming or machining operations had started was rejected. It was then reviewed by a material review board consisting of engineering, inspection, and laboratory personnel. If it were possible to utilize the defective material in some other application, then the material was dispositioned in this manner.

Sheet material that had visible surface defects, was rejected and dispositioned to remove the defective area.

SECTION 9

STATIC TEST PROGRAM

SECTION IX

STATIC TEST PROGRAM

9.1 Intent

At the outset of the titanium alloy jet pod development project, it was intended that certain portions of the pods would be fabricated from titanium alloy and that three pods would be rebuilt. After a more complete investigation and a better understanding of the information to be gained from the static testing of a complete pod, Convair proposed an alternate program.

It was felt that static testing of titanium alloy parts, manufactured for this project, as details and/or assemblies rather than testing a complete pod would yield better engineering information such as:

- 1. Obtain ultimate strength of parts.
- 2. Obtain strength of parts at correct operating temperature.
- 3. Provide a comparison between the titanium alloy parts and identical parts fabricated from aluminum and steel.
- 4. Obtain basic structural data for tension field web sections, bolts, columns, and plate stringer combinations.

9.2 Scope

The static test program of testing structural elements was divided into two phases, with WADC conducting the actual tests.


"A" Test Program

Obtain ultimate and fatigue strengths at room temperature for the titanium alloy parts that are outside the heated area of the pod, i.e., the Front Spar Web, Rear Spar Side Brace, and the Rear Spar Terminals. (Reference Figures 32, 33, and 34, pages 107, 108, and 109)

"B" Test Program

Obtain ultimate and fatigue strengths at room temperature plus short time ultimate strength, creep-fatigue strength, and creep deformation at 300°F and 600°F for structural parts within the heated area of the pod. These parts to be made from aluminum, titanium alloy, and steel. The parts are the Rear Engine Support Beam Forging and the Rear Engine Support Strut Forging.

In addition, to obtain similar data for tension field web sections, bolts, and columns composed of angle sections, barrel tube sections and two plate stringer combinations. (Reference Figure 35, page 110)



WADC TR 55-234







FIGURE 34



WADC TR 55-234

FIGURE 35





A total of 20 titanium alloy forgings, 18 steel forgings and 12 aluminum forgings were supplied to be tested.

In addition there were 39 titanium alloy, and 20 aluminum sheet metal assemblies fabricated and furnished for tests.

The titanium alloy bolts were procured from Reed and Prince Manufacturing Company and were made from RC-130B with hot, upset heads and rolled threads. (Reference Figures 36 and 37, pages 112, and 113)


9.3 Results

The results of the static test program as conducted at Headquarters, WADC, are taken from WADC Technical Notes WCLS-54-54 and WCLS-55-17. Details and photographs of the tests not included herein may be obtained from these reports.


From WCLS 54-54

Structural tests were conducted on elements of the B-36 engine pod for the purpose of proving certain parts composed of titanium to be structurally suitable for flight test, and to provide data for comparison purposes between titanium, aluminum, and steel components of the pod.

Structural tests were also conducted on miscellaneous parts (bolts, tension field beams, columns, and plate stringer combinations composed of steel, titanium, and aluminum)



WADC TR 55-234



113

CVAC P/N 36P 10356-9; rear engine support beam, CVAC P/N 36P 10353; and strut fitting rear engine support, CVAC P/N 36P 10354, withstood at least 100 percent static ultimate load for the design conditions specified in Convair Report No. FZS-36-399.

Results of the room temperature fatigue tests on the titanium elements of the engine pod, as shown in Table IV, indicate that only the rear spar side brace exhibited acceptable fatigue properties. The upper front spar strut web at 1.44 x 106 cycles and the rear engine support beam at 2.94 x 104 cycles should be considered as exhibiting undesirable fatigue tendencies. It is recognized that the fatigue cycling load level used in testing the upper front spar strut web is high when compared to the design load, and that a substantial increase in fatigue life might be realized through reduction in the load level. However, it is pointed out that detail design of the web is such that poor fatigue properties can be expected with cracks initiating in the bend radii.

The TI 150 forgings, testing under this program, are decidedly inferior to alloys which have subsequently been developed. Hydrogen embrittlement has been found to seriously effect the strength properties of this alloy in other than short time loading applications.

Recommendations

In view of the comment in the above paragraph, it is recommended that extreme caution be exercised in utilizing parts composed of TI 150A alloy in applications where failure of the parts would jeopardize personnel or equipment.

If the upper front spar strut web, CVAC P/N 36P 10355, is to be used in its present configuration, it is recommended that additional fatigue tests using a more realistic fatigue cycling load level, be conducted prior to approval.

No recommendations are made pertaining to the bolts, tension field beams, columns, or plate stringer combinations tested, since the test data is for informational purposes only. It is noted, however, that improved strength characteristics of titanium bolts may be obtained by rolling rather than cutting the threads.

From WCLS 55-17

Stress rupture tests were conducted on the rear engine support strut fitting, CVAC P/N 36P 10354, for the purpose of determining the characteristics of the part under sustained loadings. (These data are not included in this report but can be obtained from WCLS 55-17). Fatigue tests

for the purpose of obtaining allowables and data pertinent to possible subsequent supersonic designs. The tests were conducted at Headquarters, Wright Air Development Center, Wright Patterson Air Force Base, Ohio.

Fatigue tests at room temperature were conducted on the engine pod components as indicated in Table IV of this report (due to the limited load capacity of the fatigue testing equipment available, fatigue tests of the rear spar terminal, CVAC P/N 36P 10356-11, and the rear engine support fitting CVAC P/N 36P 10354, were not accomplished).

Static tests for the purpose of obtaining data pertaining to bolts, tension field web sections, and columns composed of barrel tube sections, plate stringer combinations, and angle sections, were conducted as indicated in Table V.

Fatigue tests at room temperature on steel, titanium, and aluminum bolts, and tension field beams for the purpose of obtaining comparative data were conducted as indicated in Table VI of this report.

Conclusions

As indicated in Table III, the titanium engine pod elements, Upper front spar strut web, CVAC P/N 36P 10355; rear spar side brace, CVAC P/N 36P 10356-11; rear spar terminal plate,

on miscellaneous bolts were accomplished in order to complete the program.

Based on the limited data of the tests (Tables IV and VII) it is noted that the reduction of the fatigue load level from 0-5000 pounds to 0-40 percent design ultimate (3991 pounds) increased the fatigue life of the steel fittings to the theoretical infinite value. Comparable decreases in the load level for the aluminum and titanium rear engine support beams resulted in only negligible differences in the fatigue life noted, the titanium showing minor improvement.

-	
ĮZ,	1
ď	Ì
Ē	i

6.084 6.087 6.08	Part Name &/or Number	æ/or	Material	Rockwell	Design Load Number	Temperature	timate I upported	g J
112,806 Room 100 (1) 8 Oct. 9977 Room 100 9977 Room 101 9977 Room 101 9977 Room 102 9977 Room 102 9977 Room 102 9977 Room 102 9977 Room 260 9977 C-34 PH=10790 Room 260 97 C-37 PH=10790 Room 260 95 C-30 PH=10790 Room 260 95 PH=10790 Room 100 PFeb. 95 C-30 PH=10790 Room 100 PFeb. 95 C-30 PH=10790 Room 100 PFeb. 95 C-30 PH=10790 Room 100 PFeb. 96 C-30 PH=10790 Room 100 PFeb. 97 PH=10790 Room 100 PFeb. 97 PH=10790 Room 100 PFeb. 97 PH=10790 Room 175 PFeb. 97 PH=10790 Room 100 PFeb. 97 PH=10790 P	36P 10355 Titanium 36P 10356-11 Titanium 36P 10356-11 Titanium	Titaniu Titaniu Titaniu	EEE		7809 7809 7809	Room Room Room		Aug. Sept Dec.
9977 Room 100 (1) Dec. 9977 Room 100 (1) Jan. 9977 Room 253 (1) Jan. 9977 Room 100 (1) Jan. 9977 Room 260 (1) Reb. 997 Reb. 997 Reb. 997 Reb. 995 (1) Reb. 997 Reb. 995 (1) Reb.	10356-9	Titani	Ħ		112,806	Room		oct.
9977 9977 800m 9977 9977 800m 9977 9977 800m 112 9977 900°F 101 9977 900°F 101 9977 900°F 900°F 101 9977 900°F 900°F 900°F 9077 900°F 900°	10356-9 10353	Titani Steel	Ę		94,297 9977	Room		Dec.
9977 9977 800m 112 9977 800m 112 9977 9977 800m 12 9977 9977 800m 12 9977 9077 900m 12 9977 9077 900m 12 9077 9077 900m 12 907 907 907 907 907 907 907 907 907 907	10353	Steel Steel			9977	H00m 3000F		
9977 9977 8000F 112 9977 8000F 112 9977 8000F 112 9977 8000F 112 9977 9977 8000F 112 9977 9977 8000F 112 9977 9977 8000F 112 9977 9000F 112 9977 9000F 113 9000F 114 9000F 115 9	10353	Steel			7766	600°F		
9977 9977 9977 9007 9977 9007 9077 9007 9077 9000F 9077 9000F 9000	10353	Alumin	E E		9977	700m 300 ^p	101	Jan.
C-34 PH=10790 Room 260 (1) 16 Feb. PV=977 Room 260 (1) 17 Feb. PV=977 Room 260 (1) 17 Feb. PV=977 Room 260 (1) 17 Feb. PV=977 Room 100 (1) 17 Feb. PV=977 Room 100 (1) 17 Feb. PV=977 Room 100 (1) 9 Feb. PV=977 Room 225 (1) 19 F	10353	Titaniu	i e		9977	Room	211	
C-34 PV=9977 300°P 230 [1] 17 Feb. PV=10790 600°P 235 [1] 17 Feb. PV=9977 800°P 235 [1] 12 Feb. PV=9977 800°P 235 [1] 12 Feb. PV=9977 800°P 225 [1] 9 Feb. PV=9977 800°P 225 [1] 5 Feb. PV=9977 800°P 225 [1] 17 Feb. PV=9977 800°P 175 [1] 11 Feb. PV=9977 800°P 145 [1] 11 Feb. PV	P 10353 Titanium P 10353 Titanium	Titaniu Titaniu	E C	Ĉ	9977	5000F	186	Jan
C-37 PH=10790 300°P 230 (1) 17 Feb. PV=9977 300°P 210 (1) 17 Feb. PH=10790 300°P 210 (1) 17 Feb. PH=10790 600°P 235 (1) 17 Feb. PH=10790 FH=10790 800°P 235 (1) 12 Feb. PV=9977 800°P 235 (1) 12 Feb. PV=9977 800°P 235 (1) 8 Feb. PV=9977 800°P 225 (1) 9 Feb. PV=9977 800°P 225 (1) 5 Feb. PV=9977 800°P 175 (1) 9 Feb. PV=9977 800°P 175 (1) 11 Feb. PV=9977 800°P 175 (1) 10 Feb.	10354	Steel		C-34	PV=10(90 PV=9977	IIIOON	~~	
C-37 FH=10790 300°F 210 (1) 17 Feb. Py#9977 300°F 235 (1) 12 Feb. Py#9977 Room 110 (1) 8 Feb. Py#9977 Room 225 (1) 9 Feb. Py#9977 Room 225 (1) 9 Feb. Py#9977 Room 225 (1) 9 Feb. Py#9977 Room 225 (1) 5 Feb.	36P 10354 Steel	Steel		c-37	PH=10790 PV=9977	300oF		Feb.
C-35 PH=10790 600°F 235 (1) 12 Feb. PH=10790 600°F 235 (1) 12 Feb. PH=10790 Room 110 (1) 8 Feb. PH=10790 800°F 100 (1) 9 Feb. PH=10790 Room 225 (1) 5 Feb. PW=9977 Room 225 (1) 5 Feb. PW=9977 Room 225 (1) 5 Feb. PW=9977 Room 225 (1) 1 Feb.	36P 10354 Steel	Steel		0-37	PH=10790	300°F		Feb.
B-80 PW=9977 Room 108 (1) 8 Feb. PW=9977 300°F 100 (1) 9 Feb. PW=9977 Room 225 (1) 9 Feb. PW=9977 Room 225 (1) 5 Feb. PW=9977 300°F 175 (1) 11 Feb. PW=9977 G-30 PW=9977 G-30 PW=9977 145 (1) 10 Feb.	36P 10354 Steel	Steel		c-35	FV=10790	3009 6000F	,	Feb.
B-79 FW=10790 300°F 100 (1) 9 Feb. PV=9977 Room 225 (1) 5 Feb. PV=9977 300°F 175 (1) 11 Feb. PV=9977 600°F 175 (1) 11 Feb. PV=9977 600°F 175 (1) 10 Feb. PV=9977 600°F 145 (1) 10 Feb.	36P 10354 Aluminum	Aluminur	E	в-80	FV=9977 PH=10790 B::-0077	Room		Feb.
C-30 PH=10790 Room 225 (1) 5 Feb. PV=9977 S00°F 175 (1) 11 Feb. PV=9977 C-30 PH=10790 600°F 175 (1) 11 Feb. PV=9977 600°F 145 (1) 10 Feb. PV=9077 600°F 145 (1) 10 Feb. PV=0977 600°F 145 (1)	36P 10354 Aluminum	Aluminu	Ħ	B-79	PH=10790	3000F	•	Feb.
C-30 FH=10790 300°F 175 (1) 11 Feb. PV=9977 600°F 145 (1) 10 Feb. PH=10790 600°F 145 (1) 10 Feb. PH=10770	36P 10354 Titanium	Titaniu	E	c-30	PH=10790	Коот	<u></u>	Feb.
C-30 FH*1077 600°F 145 (1) 10 Feb.	36P 10354 Titanium	Titani	E	02-3	PH=10790	3000F	~~	Feb.
	36P 10354 Titanium	Titaniu	E	0-30	FV#3311 PH#10790 PVI=9977	4 ₀ 009	~	Feb.

(1) Without Failure

TABLE IN

	Design Ulti Load Stre	Ultimate boad Strength Level		Number of Oyoles	Pass
	£087	0-5	0-5000	107 (1)	4-27 Nov. 53
-1	2444	η - 0	0-4000 2.5	2.5 x 10 ⁶	5-14 Jan. 54
-7	7445	 ₩-0	0-4000	1.44 x 10 ⁵	18-20 Jan. 54
9	7766	0-0	0-5000 1.3	1.35 x 10 ⁵	
9977	17	0	0-5000 1.5	1.53 x 10 ⁵	29 Jan. 54
9977		0-4	0-4484 2.9	2.91 × 10 ⁴	27 Jan. 54
9977	2.2	7-0	0-4484 4.3	4.35 x 10 ⁴	27 Jan. 54
99	,21 7766	12,290 0- ⁴	0-4916 2.94)4 x 10 ⁴	27 Jan. 54
9	7166	7-0	0-4916 3.1	3.17 x 10 ⁴	27 Jan. 54

(1) Without Failure

1	$\mathbb{C}_{\mathbb{C}}$ \mathbb{C} $\mathbb{C}_{\mathbb{C}}$ $\mathbb{C}_{\mathbb{C}}$ $\mathbb{C}_{\mathbb{C}}$ $\mathbb{C}_{\mathbb{C}}$ \mathbb{C} $\mathbb{C}_{\mathbb{C}}$ \mathbb{C}
Date	Jul. Jul. Jul. Jul. Jul. Jul. Jul. Jul.
Load Supported	5655 5120 5222 4128 5470 2705 2705 28705 5690 5690 5770
Temperature	8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8
Design Load	118 500 000 000 000 000 000 000 000 000 00
Rockwell	00000000000000000000000000000000000000
Material	Steel Steel Steel Steel Steel Steel Aluminum Titanium Titanium Titanium Titanium Titanium Titanium Titanium Titanium Titanium Steel
Part Name &/or Number	AN-4 Beit AN-4 Beit AN-4 Beit AN-4 Beit AN-4 Beit AN-4 Beit AN-4 Beit AN-8 B
rest No	$\begin{array}{cccccccccccccccccccccccccccccccccccc$

(Cont'	
TABLE V	STATIC TESTS

Date	28228282828282828282828282828282828282	
Load Supported	11 33 4 6 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9	
Temperature	W W W W W W W W W W W W W W W W W W W	
Design Load	36,000 000 36,000 36,000 36,000 36,000 36,000	
Rockwell		
Material	· · · · · · · · · · · · · · · · · · ·	ds Flxed
Part Name &/or Number	36FTW 598-9 36FTW 598-9 36FTW 598-9 36FTW 598-9 36FTW 598-23 36FTW 598-23 36FTW 598-19 36FTW 598-13 36FTW 598-11 36FTW 598-11 36FTW 598-12 36FTW 299-9 36FTW 299-9 36FTW 299-9 36FTW 598-25 36FTW 598-27 36FTW 598-27 36FTW 598-27 36FTW 598-27 36FTW 598-27 36FTW 598-27	
Test No	である。 のののののののでは、 でのできない。 でのできない。 でのできない。 できない	

\vdash
\Rightarrow
r-1
딈
\overline{a}
4

Test No	Part Name &/or Number	Mațerial	Rockwall	Design Load	Average Ult. Strength	Load Level	Number of Cycles	Date
,		•		080-	288	2316	(6)	
H	AN-4 Bolt	Steel		0004	000	77.00	10	
a	AN-4 Bolt	Steel		4080	5388	0-2155	\ \ \\	
~	AN-4 Bolt	Aluminum		2030	2705	0-1352	Ñ ()	
). †	AN-4 Bolt	Aluminum		2030	2705	0-1352	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	
· rc	AN-4 Bolt	Aluminum		2030	2705	0-812	\ 2 \	
νc	AN-4 Bolt	Aluminum		2030	2705	0-812	_	
۰,	AN-4 Bolt	Titanium	0-33	1	5665	0-2266	5.06 × 102	16 Mar-17 Mar 54
-α	AN-IL POLE	Titanium	0-35		5665	0-2266	_	
σ	AN-8 Bolt	Stee1	C-27	18,500	25,275	0-10,110	10, (1)	3 Mar-13 Jul 54
٦,	AN-8 Bolt	Steel	c-26	18,500	25,275	0-10,110	(2)	
3:	AN-8 Bolt	Aluminum		9180	10,400	0-5200	3.1 × 102	
12	AN-8 Bolt	Aluminum	B-68	9180	10,400	0-5200	3.2 × 105	Feb D
13	AN-8 Bolt	Aluminum	3-69	9180	10,400	0-3120	× 100	5 Feb-9 Feb 54
17.	AN-8 Bolt	Aluminum	B-71	9180	10,400	0-3120	101 10 (1)	Mar
15	AN-8 Bolt	T1tan1um	C-34		19,525	0-7810	2.68 x 10	
12	AN-8 Bolt	Titanium	0-35		19,525	0-7810	3.0 × 10+	12 Mar
12	368mw 299-11	Steel		36,000		0-14000	3.04 × 102	
-62		Aluminum		36,000		0-14000	3,14 x. 102	May- 2 Jun
161		Titanium		36,000		0-14000	105	

TABLE VII

Mate rial Design Ultimate Load Numbe r of Cycles Date Load Strength Level	Pitanium 9977 12,290 0-3991 7×10^4 5 Aug. 54	Aluminum 9977 11,210 0-3991 6.8 x 10 ⁴ 6 Aug. 5 ⁴ Steel 9977 0-3991 107(1) 6 Aug. 5 ⁴ 28 Dec. 5 ⁴	Titanium 9977 12,290 0-3991 5 x.10 ⁴ 28 Dec. 5 ⁴ 29 Dec. 5 ⁴ 29 Dec. 5 ⁴	Aluminum 9977 11,210 0-3991 2.9 x 10^4 29 Dec. 54	4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
		min c	1 nm		
Part Name &/or Number	36P 10353	36P 10353 36P 10353	36P 10353	36P 10353	
No at	10	11	13	14	

TABLE VIII

Dates	14 Jan. 55- 9 Feb. 55	10 Feb. 55 15 Feb. 55	16 Feb. 55 21 Feb. 55	21 Feb. 55	24 Feb. 55 1 Mar. 55	1 Mar. 55 7 Mar. 55	18 Mar. 54 5 Jan. 55	13 July 54- 22 July 54	5 Jan. 55- 14 Jan. 55	21 Feb. 55- 23 Feb. 55
ø v	(1)	(1)	(1)		(1)	(1)	(1)	(1)	(1)	
Number of Cycles	101	107	107	6.9×10^{5}	107	107	107	4 x 10 ⁶	107	1.03 × 10 ⁶
Load Level	0-2155	0-2155	0-1352	0-1352	0-812	0-812	0-2266	0-10,110	0-2266	0-1352
Average Ultimate Strength	5388	5388	2705	2705	2705	2705	5665	25,275	5995	2705
Design Ultimate	4080	4080	2030	2030	2030	2030		18,500		2030
]ockwell	c - 28	C-27	B-73	E-73	B-74		c - 35	c-26	C-34	B-73
Haterial	Steel	Cteel	Aluminum	Aluminum	Aluminum	Aluminum	Titanium	Steel	Titanium	Aluminum
Part Name &/or	AN-4 Bolt	AN-4 Bolt	AN-4 Bolt	AN-4 Bolt	AN-4 Bolt	AN-4 Bolt	AN-4 Bolt	AN-8 Bolt	AN-4 Bolt	AN-4 Bolt
Test No.	H.	Ø	т	†7	5	\o	∞	10	20	21

(1) Without Failure

SECTION 10

FLIGHT TEST PROGRAM

SECTION X

FLIGHT TEST PROGRAM

10.1 Summary

Upon completion of fabrication of the two flight test pods, J47 jet engines were installed and then the pods were hung on B-36D Airplane No. 51 (USAF Serial No. 44-92054) and flight tested from 11 March 1954 to 28 August 1954.

During this test period a total flight time of 183 hours was accumulated on 33 flights of the airplane. The jet engines were operated an average of 80 hours of which 67 hours were during flight.

10.2 Discussion

Since the purpose of the flight test program was to determine the serviceability of the titanium alloy jet pod nacelle components when subjected to actual service conditions, no instrumentation was installed. After each flight the titanium parts were visually inspected to determine if any failures had occurred or were suspected to occur.

Two minor failures were found after approximately 130 flight hours. These occurred in small angle stiffeners of the right hand pod box beam assembly. In each case, a crack

started from the edge of the stiffener and terminated in a bolt hole. Because the stiffeners had to pick-up an existing bolt pattern, each of the holes had short edge distance.

It was determined that these cracks did not affect the structural integrity of the pods, so the flight testing was continued.

10.3 Results

Upon completion of the flight test program, the pods were removed from the airplane and partially disassembled, and all parts were again visually inspected. In addition to the visual inspection all parts were subjected to a dye penetrant inspection and no cracks or failures were found.

The titanium alloy components were still entirely serviceable after accumulating 183 hours of flight time.